

FIG. 1




FIG. 2




FIG. 3




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B

	I	II	III	IV	V	VI	VII	VIII
V_{x1}	H	H	H	H	L	L	L	L
V_{x2}	H	H	L	L	H	H	L	L
V_{x3}	H	L	H	L	H	L	H	L
V_{g31}	V_{31}	L	V_{31}	L	V_{31}	L	H	L
V_{g32}	V_{32}	V_{32}	L	L	H	H	L	L
V_{g33}	V_{33}	H	V_{33}	H	V_{33}	H	L	H

I : NORMAL OPERATION CONDITION

VIII : ABNORMAL CONDITION (SHUTDOWN)

FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

